09/846127

Co C

HENLETT-PACKARD CO.

AND Sal Dept., Intellectual Property Section 3404 E. Harmony Road, M/S 79

Fort Collins, Colorado 80528

PATENT APPLICATION

ATTORNEY DOCKET NO. 10007794-1

January 17, 2005

Certificate
JAN 3 1 2005
of Correction

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Re: United States Patent No. 6,781,146 issued August 24,

2004 for ANNEALED TUNNELING EMITTER

Dear Sir:

Enclosed for filing (in duplicate) is a Certificate of Correction of the above-identified patent. Please record the document.

It is believed that no fees should be necessary since the errors are all Patent Office typographical errors. However, should any fees be necessary, please charge Deposit Account No. 08-2025. A duplicate copy of this letter is enclosed for that purpose.

Sincerely,

KLAAS, LAW, O'MEARA & MALKIN, P.C.

Jay K. Malkin

JKM/jlr Enclosures Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

: 6,781,146

DATED

Ŋ

: August 24, 2004

INVENTOR(S): Chen et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In The Claims

Col. 8 (line 37), delete " $1x1^{-1}$ " and insert therefor -- $1x10^{-1}$ --.

Col. 10 (line 4), delete "18" and insert therefor --18;--.

MAILING ADDRESS OF SENDER: Hewlett-Packard Company Intellectual Property Section 3404 E. Harmony Road, M/S 79 Fort Collins, CO 80528

6,781,146 PATENT NO.

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

HEWLETT-PACKARD CO. Legal Dept., Intellectual Property Section 3404 E. Harmony Road, M/S 79 Fort Collins, Colorado 80528

PATENT APPLICATION

ATTORNEY DOCKET NO. 10007794-1



January 17, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Re: United States Patent No. 6,781,146 issued August 24,

2004 for ANNEALED TUNNELING EMITTER

Dear Sir:

Enclosed for filing (in duplicate) is a Certificate of Correction of the above-identified patent. Please record the document.

It is believed that no fees should be necessary since the errors are all Patent Office typographical errors. However, should any fees be necessary, please charge Deposit Account No. 08-2025. A duplicate copy of this letter is enclosed for that purpose.

Malkin

Sincerely,

KLAAS, LAW, O'MEARA & MALKIN, P.C.

JKM/jlr

Enclosures

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

PATENT NO

: 6,781,146

DATED

: August 24, 2004

INVENTOR(S): Chen et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In The Claims

Col. 8 (line 37), delete " $1x1^{-1}$ " and insert therefor -- $1x10^{-1}$ ---

Col. 10 (line 4), delete "18" and insert therefor --18;--.

6,781,146

PATENT NO. _

No. of additional copies

MAILING ADDRESS OF SENDER: Hewlett-Packard Company Intellectual Property Section 3404 E. Harmony Road, M/S 79 Fort Collins, CO 80528